



USAID | **HAITI**
FROM THE AMERICAN PEOPLE

ENGINEERING DESIGN & CONSTRUCTION SUPERVISION PROGRAM CARACOL EKAM FINAL REPORT

Submitted August 16, 2018: Revised August 27, 2018

DISCLAIMER

This publication was produced for review by the United States Agency for International Development. It was prepared by Tetra Tech.



August 27, 2018

John Piggott
Contracting Officer's Representative
USAID/Haiti
Blvd. 15 Octobre
Tabarre 41, Tabarre Haiti


Re: Caracol EKAM Final Report
Engineering Design & Construction Supervision, Contract No. EDH-I-00-08-00027, Task Order No. AID-367-TO-14-00003

Dear Mr. Piggott:

Tetra Tech is pleased to submit for your information and records our Final Report for the above-referenced Task Order under the Indefinite Quantity Contract for Global Architecture and Engineering (A&E) Infrastructure Services Contract No. EDH-I-00-08-00027. This report is being provided pursuant to our contract and is our last deliverable.

It has been our pleasure to work with you on this project and we are pleased that together we have successfully met the objectives of this task order and, in doing so, improved the living conditions of all the residents at EKAM.

Sincerely,



Chief of Party
Tetra Tech

ENGINEERING DESIGN & CONSTRUCTION SUPERVISION PROGRAM

CARACOL EKAM FINAL REPORT

This report was prepared for the United States Agency for International Development, Contract No. EDH-I-00-08-00027-00, Task Order Number AID-521-TO-15-00001 Engineering Design and Construction Supervision Program.

Contact Information




TABLE OF CONTENTS

1.0	Introduction	1
2.0	Background.....	1
3.0	Scope of Work.....	1
3.1	Objectives.....	2
3.2	Caracol EKAM.....	2
3.2.1	Initial Inspection and Findings	2
3.2.1.1	Housing	2
3.2.1.2	Site Works	3
3.2.1.3	Other.....	3
3.2.2	Recommendations, Designs and Oversight.....	3
3.2.2.1	Recommendations	3
3.2.2.2	Designs	4
3.2.2.2.1	Housing	4
3.2.2.2.2	Sanitary.....	4
3.2.2.2.3	Other Civil	5
3.2.2.3	Oversight.....	5
3.2.3	Support for Contractual Adjustments.....	7
3.3	Terrier Rouge and Ouanaminthe.....	7
4.0	Attachments.....	7

1.0 INTRODUCTION

This final report summarizes work undertaken for the USAID Engineering Design and Construction Supervision Program in Cap-Haitian, Haiti task order. Under this program, Tetra Tech provided urgent architecture and engineering (A&E) recommendations, designs and construction supervision for the Caracol EKAM New Housing Settlement (Caracol EKAM) in the Northern Corridor. USAID's acceptance of this final report coincides with and confirms their acceptance of all deliverables under this contract. All Section F deliverables required under this contract have been uploaded to USAID's DEC website.

2.0 BACKGROUND

USAID, in cooperation with the Government of Haiti (GOH), built the Caracol EKAM New Housing Settlement (EKAM) in the Northern Corridor to provide housing for households impacted by the 2010 earthquake and other critical groups in the Northern Corridor. This 750-house settlement was constructed between October 2011 and October 2013.

In March 2014, USAID first became aware of deficiencies in both the housing and civil construction. A subsequent independent assessment of a significant sample of houses revealed design and performance deficiencies including leaking roofs, missing or sub-specification roof fasteners, sub-specification foundations, substandard concrete reinforcement in wall construction, extensive material substitutions, poor quality doors and windows, minor cracking in walls, drainage issues, exposed water pipes, poorly designed and installed water tanks, improperly installed and substandard sewer pipes, and nonfunctioning solar security lights.

In October 2014, USAID contracted Tetra Tech to provide independent Architectural and Engineering (A&E) and construction management services to inspect the EKAM site, provide A&E recommendations, manage and supervise remedial work, and provide support to USAID for contractual adjustments.

3.0 SCOPE OF WORK

Tetra Tech's primary task under this contract was to provide urgent A&E services for the Caracol EKAM site. Tetra Tech's secondary task was to assess and provide recommendations, as needed, for the civil works USAID was providing at the Terrier Rouge and Ouanaminthe housing sites. These services were spelled out in the scope of work portion of our contract as follows:

"The objective of this contract is to provide urgent A&E construction management services to: (1) conduct an inspection of the entire Caracol EKAM project, including civil works and the 750 houses; (2) make A&E recommendations and oversee the completion of remediation of identified and reparable defects in work on the project; and (3) provide support to USAID for the development of related contractual adjustments under the relevant contracts. The new contractor will conduct the inspection of the project and then manage, supervise and monitor identified remedial work that will be undertaken by THOR and CEEPCO at the EKAM site. It should be noted that since this settlement is already inhabited, so it is critical that any repairs pertaining to health and safety of the inhabitants be undertaken very quickly (fast tracked). Also, construction of repairs will have to be closely monitored to prevent any harm to the inhabitants. Close coordination with all the parties involved in this work and with the local inhabitants will be a very important project consideration.

In addition to the tasks in Caracol EKAM, the new contractor will also undertake an assessment of Terrier Rouge and Ouanaminthe housing sites and provide recommendations for remedial action if required. In these two settlements, USAID is providing infrastructure (water & sanitation, roads, storm drainage and compacted plots) for the construction of 428 houses (Terrier Rouge: 242 houses; Ouanaminthe: 184 houses). The Government of Haiti in collaboration with the Inter-American Development Bank (IDB) and Food for the Poor (FFP) is constructing the houses.”

3.1 OBJECTIVES

Tetra Tech’s initial objective at Caracol EKAM, as stated above, was to inspect the site, provide recommendations and oversee the remedial warranty repairs that were to be performed by the contractors responsible for the original work. THOR was the contractor for the housing and CEEPCO was the contractor for the civil works.

As Tetra Tech’s in-country team worked through their field inspections at the Caracol EKAM site, it quickly became apparent that the effort required to repair the existing construction deficiencies being uncovered would be extensive. Additionally, it was noted that the current storm water drainage system, even with implementing the remedial repairs required to bring it to the original “as designed” condition, was undersized because the development of a banana plantation on the property to the southwest of the site had dramatically increased surface water flow to the site. The downstream drainage path was also undersized, which had the additional effect of backing up the stormwater into the site.

Concerns with the extent of the remedial repairs required at the Caracol EKAM site caused USAID to revise Tetra Tech’s objectives. THOR and CEEPCO would not make the remedial warranty repairs. Tetra Tech would create design documents for selected repairs that would be bid upon and the construction would be supervised by Tetra Tech.

Tetra Tech’s scope of work at Terrier Rouge and Ouanaminthe was also revised after the original assessment, and it took over the monitoring of the remaining infrastructure work at both sites from PHS. That work is discussed in more detail below.

3.2 CARACOL EKAM

3.2.1 INITIAL INSPECTION AND FINDINGS

Tetra Tech spent approximately one month at the end of 2014 assessing the field conditions at Caracol EKAM, reviewing design and other documentation, and comparing that information to the as-built conditions. This assessment identified multiple deficiencies that required replacement, repair or improvement across all aspects of the work reviewed. Additional detailed information on Tetra Tech’s assessment can be found in document T-20 *EKAM Initial Field Assessment Report* dated January 19, 2015. This report has been uploaded to USAID’s Development Experience Clearinghouse (DEC) for reference.

3.2.1.1 HOUSING

The housing issues reviewed and discussed in the above referenced report related to roofing and framing of the roofs, doors/windows and associated hardware, plumbing, slab/foundation and stucco. Shortly after the submission of the field assessment report, Tetra Tech was authorized to perform destructive testing on a random selection of houses to determine if the walls were properly reinforced per the original designs. That testing determined that the houses were lacking the reinforcing shown on the original design drawings.

3.2.1.2 SITE WORKS

The site works reviewed were the water system, the sanitation/septic system and storm water drainage. The water system review looked at the well, well pump, pump building, water tower, underground water distribution system, service connections, house day tanks and how the system was being operated. The sanitation/septic system observations reviewed the sewer piping, septic tanks, leach fields (including soil conditions) and the operation of the system. The site drainage was reviewed to determine if the system was installed as originally designed and how current offsite conditions were affecting the ability of the drainage system to remove surface water from the site.

3.2.1.3 OTHER

There was additional work that was reviewed in Tetra Tech's field assessment report. This work did not neatly fit into either the site works or housing categories, so it was assigned to the "other" category. These portions of the work were the rainwater catchment system, street lighting and landscaping.

3.2.2 RECOMMENDATIONS, DESIGNS AND OVERSIGHT

USAID reviewed the initial inspection and findings discussed above and determined that the repairs required were too extensive to be undertaken by the original contractors, THOR and CEEPCO. USAID directed Tetra Tech to put together design documents for the repair work selected. These documents would then be bid and, upon award of a contract, Tetra Tech would provide construction oversight of the selected contractor.

3.2.2.1 RECOMMENDATIONS

After USAID reviewed Tetra Tech's initial findings, they selected the repairs and upgrades that they determined would best serve the community. The following repairs and upgrades were selected by USAID for Tetra Tech to provide design documentation for:

- Reinforce the masonry walls of the houses to improve their structural integrity
- Repair the roofing and roof framing
- Replace damaged doors and windows (shutters) and selected hardware
- Repaint the exterior of all houses
- Replace the individual platform sanitary systems with a site-wide system
- Make improvements to the water tower
- Upgrade the water pump house and install a chlorine metering system
- Replace all of the water distribution piping from the water tower to the houses
- Repair/replace selected existing onsite drainage culverts and swales
- Redirect water from the banana plantation around the site

Refer to Tetra Tech's assessment report for more detailed information on the selected recommendations.

3.2.2.2 DESIGNS

It was determined that the designs would be separated into discrete packages, one for the housing repairs, one for the sanitary repairs, and one for the other civil works which included the domestic water distribution system and the storm water management designs.

3.2.2.2.1 HOUSING

The housing repairs design package called for several repairs to the roof. Those repairs included the roofing itself and the roof framing. The metal roofing work included installing additional fasteners, patching leaks and installing/reinstalling flashing. The roof framing work included installing additional fasteners, additional wood blocking and properly securing the framing to the masonry walls.

Door and window repairs were also included in the housing repair package. This work entailed replacing damaged doors and windows (shutters), refinishing the doors and windows, the installation of additional hinges on the exterior doors, and the installation of concrete thresholds at the exterior doors. Note that during construction the work to the doors and windows was revised to only include the refinishing of the exterior doors and windows.

The final and most significant housing repair work was to reinforce the masonry walls based on projected seismic activity. Tetra Tech initially came up with a design that installed steel strapping around the houses which would be covered by plaster and therefore not be visible. Because this work required extensive interior and exterior work on occupied houses, USAID requested we look at different options and brought Miyamoto to the site to provide their seismic design expertise. Miyamoto suggested that 4 shear walls could be used to provide the required reinforcement and could all be completed from the outside of the house. Tetra Tech subsequently subcontracted Miyamoto to provide the design of this suggested repair. Note that during construction unforeseen conditions required modifications to the design which resulted in additional construction costs and an extension of the construction duration.

3.2.2.2.2 SANITARY

Tetra Tech initially suggested that the sanitary system collect effluent at each platform and that it be pumped through a force main to a leach field. USAID felt that it would be problematic to have multiple pumps and asked that this design be revisited. The design that was bid allowed the effluent to flow via gravity to a central lifting station where it is pumped to the leach field. Due to time constraints in looking at multiple options, survey requirements and other variables, USAID agreed that the design of the sanitary system should be bid as a design-build.

This system replaced the existing thin walled sanitary piping from the houses to the existing septic tanks in each platform. The existing septic tanks in a platform were then tied together at a manhole with the effluent then flowing to the sanitary main in the street. The sanitary main lines were provided with manholes at a maximum distance of 200' to allow for maintenance. All of the effluent from the mains flows to the lifting station where two pumps alternate pumping the effluent to the leach field for treatment. Discharge from the leach field is to the primary canal. During construction it was decided that the existing large septic tanks in the platforms be replaced with plastic tanks and that the small existing septic tanks in the platforms be bypassed.

During construction, the contractor, DFS, did not agree that this work was to be a design build. It was therefore agreed that DFS would provide survey information and Tetra Tech would take the design-build documents and turn them into a full construction set of documents.

3.2.2.2.3 OTHER CIVIL

The other civil works primarily consisted of improvements to the water supply system and the installation of a canal around the site to help alleviate flooding.

For the water supply system design, the buried schedule 5 water supply piping was replaced with schedule 80 piping. The design originally had the water piping inside the platforms but during construction it was decided to move the water lines to the outside of the platforms to limit their crossing of the sanitary lines. Additionally, the water main from the water tower was rerouted to align with proposed future development in that area. Shut off valves were placed at each platform so the day tanks at each house could be filled every other day, with ½ the residents receiving water each day. Water meters were also installed at each house to monitor usage. The well pump house was repaired and a chlorine metering system was installed. The well head had a cap installed.

The water tower had structural repairs designed to resolve defects and the platform at the top of the tower was enlarged to allow for access around the entire tank. The PVC riser was replaced with a galvanized riser.

The site drainage system design routed the water from the banana plantation around the site in a canal that was designed for a 10-year flood. The canal was designed with four culverts that utilized RCP to take the water under existing roads around the community. Onsite swales were to be restored to the original design.

Post bid, several changes were made to the site drainage design. The secondary canal at the back of the site was stabilized with a riprap wall to prevent erosion. The canal taking the storm water from the banana plantation around the site was rerouted and the culverts were changed from RCP to box culverts. Note that the onsite swale work was removed from the contractors' scope at this time, but additional onsite swale repairs were added back into the project in 2018. Off-site improvements to the secondary and primary canals were also added to DFS's scope of work post bid.

In 2018 road restoration work was added based upon requests from the community. For this work approximately 6" of the existing road surface was removed and replaced with gravel.

3.2.2.3 OVERSIGHT

In January 2016 Tetra Tech submitted their Quality Assurance (QA) plan to USAID which described the methodology we would use during construction to monitor DFS's work and progress. The following items are covered in this QA plan:

- Meetings and reports
- Scope verification
- Codes and Standards
- Field observations
- Testing
- As-built drawings
- Environmental Compliance
- Quality control documents

- Health and safety
- Project schedule
- Submittal review
- Invoice review
- Closeout procedures

For additional information on any of the above oversight issues please refer to our QA plan which has been uploaded to the DEC site for reference.

Below is a brief overview of some of the oversight details.

USAID awarded the construction contract to DFS in September 2015 and in October DFS began mobilizing to the site and submitting administrative and technical submittals for the project. On November 20th DFS was issued a partial Notice to Proceed (NTP) by USAID. This allowed them to start work at Terrier Rouge and the water tower at EKAM. Because work was authorized to begin, Tetra Tech held their first project meeting with DFS on November 26, 2015. All weekly construction meeting reports were transmitted to USAID via email on a weekly basis. These meeting reports detail the particular construction concerns being addressed at the time of their creation. That granular detail is excluded from this final report.

Tetra Tech staff monitored construction activities associated with the partial NTP on a daily basis. Additionally, Tetra Tech began reviewing submittal, payment applications, requests for information (RFI) and other documents as needed. These daily activities and tasks are summarized in Tetra Tech's weekly reports which were transmitted to USAID weekly via email.

Part of the design requirements of this project was for the contractor to complete work on a model house prior to being allowed to start that portion of the housing work. As the shear wall installation work was on the critical path, DFS began shear wall work on three model houses which were selected because they covered all of the shear wall conditions. Miyamoto oversaw the fabrication of these shear wall "mock ups". This process took several months to complete, but this step was necessary to ensure that DFS understood clearly what was expected as they would have to fabricate 3000 shear walls for this project.

In anticipation of work starting on this project and, in particular, the housing work, Tetra Tech began interviewing local engineering firms to provide full-time on-site construction monitoring and community liaison services. Tetra Tech selected L'Atelier to be its in-country field inspectors. In February 2016, L'Atelier started training to become familiar with the project scope and their responsibilities. In March of 2016, Tetra Tech's field inspectors began surveying each house to document the actual existing conditions prior to DFS starting their work. These inspections and the documentation of the repairs completed were provided to USAID as a part of DFS's closeout documentation for the Housing works.

With its staff fully trained and work underway, Tetra Tech continued monitoring construction progress as DFS began additional portions of the work. The work was rolled out as follows:

- 1 Shear walls
- 2 Canal work starting with the secondary canal then culverts

- 3 Sanitary work starting with the manholes
- 4 Roof repairs
- 5 Water system repairs
- 6 Road repairs

Throughout the project, Tetra Tech monitored construction and kept USAID informed of progress and concerns. If concerns were not being addressed by DFS, Tetra Tech issued a non-conformance report on the issue to highlight its importance, bring it to resolution and prevent it from becoming a punchlist item. When a portion of the work was complete our team inspected the work and provided DFS with a final punchlist that was finished before the work was considered complete. These non-conformance reports and all other construction documentation are included in DFS's closeout documentation.

3.2.3 SUPPORT FOR CONTRACTUAL ADJUSTMENTS

Because USAID decided to not have the existing contractors, CEEPCO and THOR, provide the remedial repairs, this portion of Tetra Tech's original scope of work was not required and our efforts were refocused on monitoring the construction repairs undertaken by DFS as discussed above in oversight.

3.3 TERRIER ROUGE AND OUANAMINTHE

Tetra Tech was asked to review the civil works being undertaken by CEEPCO at Terrier Rouge and Ouanaminthe. Upon our completion of this review we were tasked with monitoring CEEPCO's completion of the repairs to the water towers and septic tank installations at both sites and the remedial repairs to the leaching fields at Terrier Rouge. When this work was completed Tetra Tech worked with CEEPCO and USAID to closeout these projects. The O&M manuals for this work were given to Tetra Tech by CEEPCO, but USAID never took possession of them. PDF's of these manuals are submitted as an annex to this document for reference.

Additionally, Tetra Tech was asked to provide designs at Terrier Rouge for a community wide sanitary leach field system, similar to the one at EKAM, and additional storm water mitigation designs. Tetra Tech completed these designs and provided them to USAID (document T-144) but the work was never implemented.

The initial bid package for the repairs at EKAM also included work at Terrier Rouge and Ouanaminthe. This scope of work was not designed by Tetra Tech, but the construction monitoring of the work was included in our scope.

The work at Terrier Rouge consisted of grading and stormwater improvements, pond dewatering, and main road swale improvements. The grading and Stormwater improvements were completed by DFS as described with some changes to the fence details. The pond dewatering scope was removed from DFS's contract and not done. The main road swale work was revised by USAID to include only the main road swale across the street from the site and not the scope shown on the bid drawings.

The work at Ouanaminthe, which consisted of access road improvements, was undertaken by a government of Haiti agency and was therefore removed from DFS's scope of work.

4.0 ATTACHMENTS

1. Operations and Maintenance manuals for Terrier Rouge and Ouanaminthe – CEEPCO (submitted as a separate document)
2. Final condition documentation of all aspects of the repair work at EKAM.

USAID/Haiti

Office of Acquisition and Assistance

Bld. 15 Octobre

Tabarre 41, Tabarre Haiti

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: __15/08/18__

Location: EKAM Village, Caracol, Haïti

Platform Number : B5-41

Representative Photo Documentation

B5-41



Photo #	Description
1	Platform view

Representative Photo Documentation	
B5-41-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B5-41-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B5-41-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B5-41-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
B5-41-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B5-41-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B5-41-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
B5-41-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: __15/08/18__

Location: EKAM Village, Caracol, Haïti

Platform Number : B5-42

Representative Photo Documentation

B5-42



Photo #	Description
1	Platform view

Representative Photo Documentation	
B5-42-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B5-42-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
B5-42-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B5-42-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B5-42-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B5-42-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B5-42-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
B5-42-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: __15/08/18__

Location: EKAM Village, Caracol, Haïti

Platform Number : B5-43

Representative Photo Documentation

B5-43



Photo #	Description
1	Platform view

Representative Photo Documentation	
B5-43-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B5-43-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B5-43-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B5-43-D	
	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B5-43-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B5-43-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B5-43-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B5-43-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: __15/08/18__

Location: EKAM Village, Caracol, Haïti

Platform Number : B6-37

Representative Photo Documentation

B6-37



Photo #	Description
1	Platform view

Representative Photo Documentation	
B6-37-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B6-37-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B6-37-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B6-37-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
B6-37-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B6-37-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
B6-37-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B6-37-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: __ 15/08/18 __

Location: EKAM Village, Caracol, Haïti

Platform Number : B6-38

Representative Photo Documentation

B6-38



Photo #	Description
1	Platform view

Representative Photo Documentation	
B6-38-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B6-38-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B6-38-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B6-38-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B6-38-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
B6-38-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
B6-38-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: __15/08/18__

Location: EKAM Village, Caracol, Haïti

Platform Number : B6-39

Representative Photo Documentation

B6-39



Photo #	Description
1	Platform view

Representative Photo Documentation	
B6-39-A	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B6-39-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B6-39-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
B6-39-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
B6-39-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B6-39-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
B6-39-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
B6-39-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: __15/08/18__

Location: EKAM Village, Caracol, Haïti

Platform Number : P04

Representative Photo Documentation

P04



Photo #	Description
1	Platform view

Representative Photo Documentation

P04-A



Photo #	Description
1	Front



Photo #	Description
2	Behind



Photo #	Description
3	Roof

Representative Photo Documentation	
P04-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P04-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P04-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P04-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P04-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P04-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P04-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P04-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P04-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P04-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P04-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P04-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P04-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P04-O	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P04-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P04-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof



Photo #	Description
2	Behind

Representative Photo Documentation	
P04-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P04-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P04-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P05

Representative Photo Documentation	
P05	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P05-A	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P05-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P05-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P05-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P05-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation				
P05-F				
				
Photo #	Description			
1	Front			
				
Photo #	Description			
3	Roof			
Photo #	Description			
2	Behind			

Representative Photo Documentation	
P05-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P05-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P05-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P05-J	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P05-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P05-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P05-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P05-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P05-O	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P05-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P05-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P05-R	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P05-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P05-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works
Location: EKAM Village, Caracol, Haïti
Platform Number : P06

Date: 15/08/18

Representative Photo Documentation	
P06	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P06-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P06-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P06-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P06-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P06-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P06-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P06-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P06-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P06-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation

P06-J



Photo #	Description
1	Front
	
Photo #	Description
3	Roof



Photo #	Description
2	Behind

Representative Photo Documentation	
P06-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P06-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P06-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P06-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P06-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P06-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P06-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P06-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P06-S	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P06-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works
Location: EKAM Village, Caracol, Haïti
Platform Number : P07

Date: 15/08/18

Representative Photo Documentation	
P07	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P07-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P07-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P07-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P07-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P07-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P07-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P07-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P07-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P07-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation

P07-J



Photo #	Description
1	Front



Photo #	Description
2	Behind



Photo #	Description
3	Roof

Representative Photo Documentation	
P07-K	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P07-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P07-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P07-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P07-O	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P07-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P07-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P07-R	
	
Photo #	Description
1	Front
 	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P07-S	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P07-T	
	
Photo #	Description
1	Front
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works
Location: EKAM Village, Caracol, Haïti
Platform Number : P09

Date: 15/08/18

Representative Photo Documentation	
P09	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P09-A	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P09-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind


Representative Photo Documentation	
P09-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P09-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P09-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P09-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P09-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P09-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P09-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P09-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P09-K	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P09-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P09-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P09-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P09-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P09-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P09-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P09-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P09-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P09-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works
Location: EKAM Village, Caracol, Haïti
Platform Number : P10

Date: 15/08/18

Representative Photo Documentation	
P10	
Photo #	
	Description
1	Platform view

Representative Photo Documentation	
P10-A	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P10-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P10-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P10-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P10-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P10-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P10-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P10-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P10-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation

P10-J



Photo #	Description
1	Front



Photo #	Description
3	Roof



Photo #	Description
2	Behind

Representative Photo Documentation	
P10-K	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof


Representative Photo Documentation	
P10-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P10-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P10-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P10-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P10-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P10-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P10-R	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P10-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P10-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms


Project: EKAM Emergency Repairs Works
Location: EKAM Village, Caracol, Haïti
Platform Number : P11

Date: 15/08/18

Representative Photo Documentation	
P11	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P11-A	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P11-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P11-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P11-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P11-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P11-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P11-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P11-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P11-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P11-J	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P11-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P11-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P11-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof


Representative Photo Documentation	
P11-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P11-O	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P11-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P11-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P11-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P11-S	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P11-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works
Location: EKAM Village, Caracol, Haïti
Platform Number : P12

Date: 15/08/18

Representative Photo Documentation	
P12	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P12-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P12-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P12-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P12-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P12-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P12-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P12-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P12-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P12-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P12-J	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P12-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P12-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P12-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P12-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P12-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P12-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P12-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P12-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P12-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P12-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works
Location: EKAM Village, Caracol, Haïti
Platform Number : P13

Date: 15/08/18

Representative Photo Documentation	
P13	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P13-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P13-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P13-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation			
P13-D			
			
Photo #	Description	Photo #	Description
1	Front	2	Behind
			
Photo #	Description		
3	Roof		

Representative Photo Documentation	
P13-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P13-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P13-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P13-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P13-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation

P13-J



Photo #	Description
1	Front



Photo #	Description
3	Roof



Photo #	Description
2	Behind

Representative Photo Documentation	
P13-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P13-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P13-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P13-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P13-O	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P13-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P13-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P13-R	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P13-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P13-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P14

Representative Photo Documentation	
P14	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P14-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P14-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P14-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P14-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P14-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P14-F	
	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P14-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P14-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation				
P14-I				
				
Photo #	Description			
1	Front			
				
Photo #	Description			
3	Roof			
Photo #	Description			
2	Behind			

Representative Photo Documentation	
P14-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P14-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P14-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P14-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P14-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P14-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P14-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P14-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P14-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P14-S	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P14-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P16

Representative Photo Documentation

P16



Photo #	Description
1	Platform view

Representative Photo Documentation	
P16-A	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P16-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-J	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-K	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation				
P16-N				
				
Photo #	Description			
1	Front			
				
Photo #	Description			
3	Roof			
Photo #	Description			
2	Behind			

Representative Photo Documentation	
P16-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P16-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P16-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P16-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works
Location: EKAM Village, Caracol, Haïti
Platform Number : P17

Date: 15/08/18

Representative Photo Documentation	
P17	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P17-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation

P17-B



Photo #	Description
1	Front
	
Photo #	Description
3	Roof



Photo #	Description
2	Behind

Representative Photo Documentation	
P17-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P17-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P17-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation

P17-F



Photo #	Description
1	Front



Photo #	Description
2	Behind




Photo #	Description
3	Roof

Representative Photo Documentation	
P17-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P17-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P17-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P17-J	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P17-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P17-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P17-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P17-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P17-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P17-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P17-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P17-R	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P17-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P17-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works
Location: EKAM Village, Caracol, Haïti
Platform Number : P18

Date: 15/08/18

Representative Photo Documentation	
P18	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P18-A	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P18-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P18-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P18-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P18-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P18-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P18-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P18-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P18-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation

P18-J



Photo #	Description
1	Front
	
Photo #	Description
3	Roof



Photo #	Description
2	Behind

Representative Photo Documentation	
P18-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P18-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P18-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P18-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P18-O	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P18-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P18-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P18-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P18-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P18-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P20

Representative Photo Documentation	
P20	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P20-A	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P20-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P20-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P20-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P20-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P20-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P20-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P20-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P20-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P20-J	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P20-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation

P20-L



Photo #	Description
1	Front
	
Photo #	Description
3	Roof



Photo #	Description
2	Behind

Representative Photo Documentation	
P20-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P20-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P20-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P20-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P20-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P20-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P20-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P20-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P21

Representative Photo Documentation	
P21	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P21-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P21-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P21-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P21-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P21-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P21-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P21-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P21-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P21-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
Photo #	Description
3	Roof

Representative Photo Documentation	
P21-J	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation			
P21-K			
			
Photo #	Description		
1	Front		
			
Photo #	Description		
3	Roof		
Photo #	Description		
2	Behind		

Representative Photo Documentation	
P21-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P21-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P21-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P21-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P21-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P21-Q	
	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P21-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P21-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P21-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P22

Representative Photo Documentation	
P22	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P22-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P22-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P22-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P22-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P22-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P22-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P22-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation

P22-H



Photo #	Description
1	Front
	
Photo #	Description
3	Roof



Photo #	Description
2	Behind

Representative Photo Documentation	
P22-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P22-J	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P22-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P22-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P22-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P22-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P22-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P22-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P22-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P22-R	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P22-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P22-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works
docs

Date: EKAM Platforms

Location: EKAM Village, Caracol, Haïti
Platform Number : P23

Representative Photo Documentation	
P23	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P23-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P23-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P23-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P23-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P23-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P23-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P23-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P23-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P23-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P23-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P23-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P23-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P23-R	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P23-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P23-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: __15/08/18__

Location: EKAM Village, Caracol, Haïti

Platform Number : P24

Representative Photo Documentation	
P24	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P24-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P24-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P24-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P24-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P24-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P24-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P24-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P24-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P24-O	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P24-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P24-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P24-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P24-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P24-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P25

Representative Photo Documentation	
P25	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P25-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P25-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P25-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P25-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P25-J	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P25-K	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P25-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P25-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P25-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P25-O	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P25-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P25-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P25-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P25-S	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti


Platform Number : P26

Representative Photo Documentation	
P26	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P26-A	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P26-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof


Representative Photo Documentation	
P26-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P26-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P26-J	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-K	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-O	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P26-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P26-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P41

Representative Photo Documentation

P41



Photo #	Description
1	Platform view

Representative Photo Documentation	
P41-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind


Representative Photo Documentation	
P41-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P41-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P41-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P41-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P41-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind


Representative Photo Documentation	
P41-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P41-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P41-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P41-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P41-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P41-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P41-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P41-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P41-O	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P41-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P41-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P41-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P41-S	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P41-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P42

Representative Photo Documentation

P42



Photo #	Description
1	Platform view

Representative Photo Documentation	
P42-A	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P42-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P42-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P42-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P42-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P42-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P42-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P42-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P42-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P42-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P42-K	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P42-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P42-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P42-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P42-O	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation				
P42-P				
				
Photo #	Description			
1	Front			
				
Photo #	Description			
3	Roof			
Photo #	Description			
2	Behind			

Representative Photo Documentation	
P42-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P42-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P42-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P42-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P45

Representative Photo Documentation

P45



Photo #	Description
1	Platform view

Representative Photo Documentation	
P45-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P45-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P45-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P45-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P45-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P45-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P45-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P45-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P45-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P45-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P45-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P45-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P45-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation			
P45-N			
			
Photo #	Description		
1	Front		
			
Photo #	Description		
3	Roof		

Representative Photo Documentation	
P45-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P45-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P45-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P45-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P45-S	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P45-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P46

Representative Photo Documentation	
P46	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P46-A	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P46-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P46-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P46-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P46-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P46-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P46-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P46-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P46-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P46-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation				
P46-K				
				
Photo #	Description			
1	Front			
				
Photo #	Description			
3	Roof			
Photo #	Description			
2	Behind			

Representative Photo Documentation	
P46-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P46-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P46-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P46-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P46-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P46-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P46-R	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P46-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P46-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P47

Representative Photo Documentation	
P47	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P47-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P47-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation

P47-C



Photo #	Description
1	Front
	
Photo #	Description
3	Roof



Photo #	Description
2	Behind

Representative Photo Documentation	
P47-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P47-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation

P47-F



Photo #	Description
1	Front
	
Photo #	Description
3	Roof



Photo #	Description
2	Behind

Representative Photo Documentation	
P47-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P47-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P47-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P47-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P47-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P47-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P47-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P47-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P47-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P47-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P47-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P47-R	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P47-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P47-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P48

Representative Photo Documentation	
P48	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P48-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation

P48-B



Photo #	Description
1	Front
	
Photo #	Description
3	Roof



Photo #	Description
2	Behind

Representative Photo Documentation	
P48-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P48-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P48-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P48-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P48-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P48-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P48-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof


Representative Photo Documentation	
P48-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P48-K	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P48-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P48-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P48-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P48-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P48-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind


Representative Photo Documentation	
P48-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P48-R	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P48-S	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P48-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works
Location: EKAM Village, Caracol, Haïti
Platform Number : P49

Date: 15/08/18

Representative Photo Documentation	
P49	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P49-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P49-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P49-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P49-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P49-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P49-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P49-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind


Representative Photo Documentation	
P49-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P49-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P49-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P49-K	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P49-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P49-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P49-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P49-O	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P49-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P49-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P49-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P49-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P49-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P50

Representative Photo Documentation	
P50	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P50-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P50-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P50-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind


Representative Photo Documentation	
P50-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P50-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P50-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P50-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P50-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P50-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P50-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P50-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P50-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P50-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P50-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P50-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P50-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P50-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P50-R	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P50-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P50-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P51

Representative Photo Documentation	
P51	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P51-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P51-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P51-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P51-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P51-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P51-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P51-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P51-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P51-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P51-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P51-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P51-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P51-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P51-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P51-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation	
P51-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P51-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P51-R	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P51-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P51-T	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Completion Package - Platforms

Project: EKAM Emergency Repairs Works
Location: EKAM Village, Caracol, Haïti
Platform Number : P52

Date: 15/08/18

Representative Photo Documentation	
P52	
	
Photo #	Description
1	Platform view

Representative Photo Documentation	
P52-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P52-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P52-C	
	
Photo #	Description
1	Front
 	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P52-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P52-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P52-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P52-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P52-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P52-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P52-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P52-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P52-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P52-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P52-N	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P52-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P52-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P52-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P52-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P52-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P52-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P53

Representative Photo Documentation

P53



Photo #	Description
1	Platform view

Representative Photo Documentation	
P53-A	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P53-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P53-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P53-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P53-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P53-F	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P53-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P53-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P53-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P53-J	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P53-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P53-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P53-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P53-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P53-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind


Representative Photo Documentation	
P53-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P53-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P53-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P53-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P53-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P54

Representative Photo Documentation

P54



Photo #	Description
1	Platform view

Representative Photo Documentation	
P54-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P54-B	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P54-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P54-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P54-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P54-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof


Representative Photo Documentation	
P54-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P54-H	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P54-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation

P54-J



Photo #	Description
1	Front



Photo #	Description
2	Behind



Photo #	Description
3	Roof

Representative Photo Documentation	
P54-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P54-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P54-M	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P54-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P54-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P54-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P54-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
Photo #	Description
2	Behind

Representative Photo Documentation			
P54-R			
			
Photo #	Description		
1	Front		
			
Photo #	Description		
3	Roof		
Photo #	Description		
2	Behind		

Representative Photo Documentation	
P54-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P54-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works

Date: 15/08/18

Location: EKAM Village, Caracol, Haïti

Platform Number : P55

Representative Photo Documentation

P55



Photo #	Description
1	Platform view

Representative Photo Documentation	
P55-A	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P55-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P55-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P55-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P55-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P55-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P55-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P55-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P55-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P55-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P55-K	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P55-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P55-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P55-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P55-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P55-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P55-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P55-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P55-S	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P55-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works
Location: EKAM Village, Caracol, Haïti
Platform Number : P56

Date: 15/08/18

Representative Photo Documentation	
P56	
	
Photo #	Description
1	Platform view

Representative Photo Documentation

P56-A



Photo #	Description
1	Front
	
Photo #	Description
3	Roof



Photo #	Description
2	Behind

Representative Photo Documentation	
P56-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P56-C	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P56-D	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P56-E	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P56-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P56-G	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P56-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P56-I	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P56-J	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P56-K	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof


Representative Photo Documentation	
P56-L	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P56-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P56-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P56-O	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P56-P	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P56-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P56-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P56-S	
	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P56-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Completion Package - Platforms

Project: EKAM Emergency Repairs Works
Location: EKAM Village, Caracol, Haïti
Platform Number : P57

Date: 15/08/18

Representative Photo Documentation

P57



Photo #	Description
1	Platform view

Representative Photo Documentation	
P57-A	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P57-B	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P57-C	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation	
P57-D	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P57-E	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P57-F	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P57-G	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P57-H	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P57-I	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Representative Photo Documentation

P57-J



Photo #	Description
1	Front



Photo #	Description
3	Roof



Photo #	Description
2	Behind

Representative Photo Documentation	
P57-K	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P57-L	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind


Representative Photo Documentation	
P57-M	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P57-N	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P57-O	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P57-P	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P57-Q	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof

	
Photo #	Description
2	Behind

Representative Photo Documentation	
P57-R	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P57-S	
	
Photo #	Description
1	Front
	
Photo #	Description
2	Behind
	
Photo #	Description
3	Roof

Representative Photo Documentation	
P57-T	
	
Photo #	Description
1	Front
	
Photo #	Description
3	Roof
	
Photo #	Description
2	Behind

Completion Package - Sanitary

Project: EKAM Emergency Repairs Works

Date: __15/08/18__

Location: EKAM Village, Caracol, Haïti

Representative Photo Documentation	
Sanitary System	
	
Photo #	Description
1	Leach field
	
Photo #	Description
2	Platform with benches protecting septic tanks and manholes

	
Photo #	Description
3	Lifting station
	
Photo #	Description
4	Typical manhole in road

Completion Package – Stormwater

Project: EKAM Emergency Repairs Works

Date: __15/08/18__

Location: EKAM Village, Caracol, Haiti

Representative Photo Documentation	
Stormwater	
	
Photo #	Description
1	Typical Road conditions
	
Photo #	Description
2	Canal

	
Photo #	Description
3	Culvert and overflow
	
Photo #	Description
4	Canal and road with swales



Photo #	Description
5	Canal



Photo #	Description
6	Culvert

	
Photo #	Description
7	Canal
	
Photo #	Description
8	Secondary canal

	
Photo #	Description
9	Typical concrete swale

Completion Package – Water System

Project: EKAM Emergency Repairs Works

Date: __15/08/18__

Location: EKAM Village, Caracol, Haïti

Representative Photo Documentation	
Water System	
	
Photo #	Description
1	Water tower and pump house
	
Photo #	Description
2	Water tower

USAID/Haiti

Office of Acquisition and Assistance

Bld. 15 Octobre

Tabarre 41, Tabarre Haiti